

AZIMUT 46 FLY

<http://www.ads-marine.com/si/ponudba-plovil/1283-azimut-46-fly-1>



OSNOVNI PODATKI

Graditelj: Azimut	Model: 46 Fly
Letnik: 2000	Modelno leto: 2007
Dolžina (m): 14,93	Širina (m): 4,43
Ugrez (m): 1,20	Teža (kg): 17000
Kabine: 2	Ležišča: 4
Kopalnice: 2	Voda (Lt): 550
Zastava: Austria	Lokacija: North Adriatic
Država: Croatia	

MOTOR

Proizvajalec: Caterpillar	Model: 3208 DITA
Število motorjev: 2	Moč (HP): 2x 457
Število ur motorja: 1748	Vrsta goriva: diesel
Gorivo (Lt): 1500	Potovalna hitrost (Vozli): 21
Maksimalna hitrost (Vozli): 26	Poraba (Lt/h): 120

Cena: 199.000,00 €

DDV vključen: Da

NAVIGATION AND ELECTRONICS:

Navigation system Raymarine E90/W
Autopilot St6000+ Raymarine
Tridata St60
VHF radio Shipmate

Flybridge:

Navigation system Raymarine E90/W
Autopilot St6001 Raymarine
VHF radio Shipmate
Chain counter Quick
Search light

ENTERTAINMENT:

Tv Silva Schneider in master cabin
Boss marine radio with speakers
Sony cd changer CDX-605
Internet router Fritzbox

GALLEY AND WATER SYSTEM:

Kitchen: el. cooktop Candy with 4 plates, double sink, refrigerator Coolmatic with freezer
Flybridge: refrigerator Isotherm

Water heater



2x Vacuflush toilets

PROPULSION, POWER AND AIR-CONDITIONING:

2x Caterpillar 3208DITA engines (457hp each)
Bow thruster Vetus
El. flaps Bennett
Kohler generator 9kW
Inverter 6kW
Air conditioning SMXir in every cabin
2x Servise Viktron 330Ah lithium batteries (NEW 2024)

MOORING AND ANCHORING:

El. anchor windlass Quick
Ultra marine anchor stainless steel
Anchor chain 10mm stainless steel 100m (NEW2025)

GENERAL:

Hydraulic gangway Opacmare
Teak cockpit and bathing platform (Renewed 2013)
Bimini top on flybridge (NEW 2023)
Covers for all windows NEW 2023)
Bow and fly sunbathing cushions (NEW 2023)
Bed mattresses replaced (NEW 2023)
Carpets in saloon replaced (NEW 2023)
Shower on stern
Swimming ladder on stern
Solar panels

The engines are meticulously serviced annually by mechanic. In 2023 the diesel tanks and heat exchangers were cleaned, and in 2025 both turbochargers were completely overhauled.

The boat needs antiosmosis treatment, the seller will bear the repair cost.

HIN *****E000 (production 05-2000, model 2000)

Broker's comission excluded



